Manhole In	spection Summary	Manhole # S25I025MH
Printed On: 12/1	6/2008	Page 1 of 3
Inspection	☐ Is Incomplete Rating: 4) Poor	
Record Plat: 25	Node: 025 Status: Found	Insp Date: 3/17/08 2:10 PM
Incomplete Comments Crew: FW/DH		
		Inspector: dhinton
		Firm: PER
Location	Address: BEHIND 1235 W.Lombard ST.	Cross Street: S.STOCKTON ST.
Manhole	Type: Terminal Location: Alley	Ground Conditions: Dry
	☐ Prev. Rehab Weather: Dry	Subject To Ponding: None
Comments		
Cover	Shape: Circular Diameter: 25. (in.) 5	Length: 0 (in.) Dist A/B Grade: 0 (in.)
	Type: Sanitary Condition: Sound	Cover Material: Cast Iron
Properties:	☐ Bolted ☑ Vented ☐ Water Tight ☐ W	Vater Tight Insert
Frame Offset: 0.5 (in.) Condition: ✓ Sound □ Cracked □ Leaks		
Chimney / Frame Adjustment		
Condition: ☐ Sound ☐ Cracked ☐ Root Intrusion ☐ Loose Brick ✓ Deteriorated		
Infiltration:	☐ None ☐ Joint ☐ Cracks ✓ Mortar ☐	Roots Wall
Corbel	Material: Brick	Type: Concentric/Eccentric
Condition:	✓ Sound ☐ Cracked ☐ Root Intrusion ☐	Loose Brick
Infiltration:	☐ None ☐ Joint ☐ Cracks ☐ Mortar	☐ Roots ✓ Wall
Barrel Material: Brick Parged		
Shape: Circular Diameter: 42 (in.) Length: 0 (in.)		
Condition:	✓ Sound ☐ Cracked ☐ Root Intrusion ☐	Loose Brick Deteriorated
Infiltration:	☐ None ☐ Joint ☐ Cracks ☐ Mortar	☐ Roots ✓ Wall
Bench	Exists Material:	Parged
Condition:	Sound Cracked Root Intrusion	Deteriorated Leaks Debris
Channel Material: Unknown Parged		
Channel Exposure: Fully Open Junc Dist: 0 nearest .5 ft. Azimuth: 0		
Condition:	☐ Sound ☐ Cracked ☐ Root Intrusion ☐	Deteriorated Leaks
Steps Count: 4 Missing: 0 Corroded		
Surcharge	Evidence Of Surcharge Depth: 0 (ft.)	Active Surcharge Present

Manhole Inspection Summary

Manhole # \$25I__025MH

Printed On: 12/16/2008 Page 2 of 3

Location View



Defect 4



CORRODED STEPS AND DEBRIS AT BOTTOM OF MANHOLE

Defect 2



EVIDENCE OF INFILTRATION AT CORBEL AND BARREL

Top View



Defect 3



BARREL INFILTRATION

Defect 1



MISSING MORTAR AT THE CHIMNEY WITH EVIDENCE OF INFILTRATION TO THE CORBEL

Manhole Inspection Summary

Manhole # \$25I__025MH

12 O'Clock Outflow

Printed On: 12/16/2008 Page 3 of 3

8 in. Circular Gravity Sewer Pipe Out @ 12 OClock



Pipe Height: **8.4** (in.) Rod and Bar (Angled)

Pipe Material: Clay

Invert Depth: 6.92 (ft.) Flow Characteristics: None

Silt Depth: **0** (in.) Deposits Extent:

Infiltration: None Pipe Seal Cond: Sound

Drop: **None**

Connects To: **Manhole**Possible Illicit Connection